



## TECHNICAL SPECIFICATIONS

### **DOST-STII AIR CONDITIONER MAINTENANCE SERVICE (AC CLEANING)**

Labor/services for the Air Conditioner Maintenance Service of 55 Air Conditioning Units in various offices.

**Window Type** : 28 units  
**Floor Mounted Type** : 20 units  
**Split Type** : 7 units

#### **Scope of Works:**

1. Cleaning of air conditioning unit's external front covers and panels.
2. Cleaning of air conditioning unit's filters.
3. Cleaning of air conditioning unit's blower fan blade.
4. Cleaning of air conditioning unit's evaporator coils.
5. Cleaning of air conditioning unit's condensation water drainage pan.
6. Checking and flushing of air conditioning unit's condensation water drainage pipe.




Republic of the Philippines  
**DEPARTMENT OF SCIENCE AND TECHNOLOGY**  
**SCIENCE AND TECHNOLOGY INFORMATION INSTITUTE**




**ISO 9001:2015**  
Certificate No. 50500772 QM15

## Technical Working Group – Infrastructure



**MARIO B. BUARAO JR.**

Member



**CARLO O. NEBRIA**

Member



**GERARDO C. DE JESUS**

Chairperson